


The Hot Work 35 ft (11m) Rule



1. Remove or shield from sparks all potential fuels within 35 ft (11m) of the work area. In this case, the paint cart and palletized storage have been moved.
2. Empty racks on which the work is to be done on all storage.
3. Close the fire doors and seal floor openings such that the area surrounding process pipes with noncombustible caulking.
4. Cover heavy combustible storage that is impractical to move with the fire-resistant tarpaulin.